

Oil Field Environmental Incident Summary

Incident: 20131202072910 **Date/Time of Notice:** 12/02/2013 0700

Responsible Party: XTO Energy INC.

Well Operator: XTO ENERGY INC.

Well Name: CLYDE HAUGE 11X-13

Field Name: DOLLAR JOE

Well File #: 21495

Date Incident: 12/1/2013 **Time Incident:** 0707

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 97

Sec: 13

Qtr:

Location Description:

Submitted By: Scot Richardson

Received By:

Contact Person: Scot Richardson
P.O Box 1589
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	barrels	5	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

C Company is performing the clean-up.

Wastes Disposal Location: PDI

Agencies Involved:

Updates

Date: 12/2/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow, remained on location within the diking, according to the report. NDIC retains oversight.